

VEHICLE INSPECTION REPORT

069171

Jacobsen R311T

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date		Colour		Gearbox	Hydrostatic
Year	UNKNOWN	VIN		Axle Combi	4WD
Mileage	1,023 Hours Not Warranted	Body Style	Ride on Mower		
Fuel Type	Diesel	Keys	1		

INTERMITTENT TRANSMISSION ISSUE

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



